

Oil Field Environmental Incident Summary

Incident: 20130103103225 **Date/Time of Notice:** 01/03/2013 10:11

Responsible Party: Encore Energy Partners Operating LLC

Well Operator: ENCORE ENERGY PARTNERS OPERATING LLC

Well Name: STEVENS 1

Field Name: BUFFALO WALLOW

Well File #: 5234

Date Incident: 1/2/2013 **Time Incident:** 11:40

Facility ID Number:

County: MCKENZIE

Twp: 148

Rng: 100

Sec: 7

Qtr: SE NW

Location Description: Release stayed on Facility Location.

Submitted By: Kevin Grindeland

Received By:

Contact Person: Bart Brinkerhoff
Box 569
Powell, wy 82435

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Miles

Distance Nearest Water Well: 1 Miles

Type of Incident: Treater Popoff

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	20	barrels	19.5	barrels	19.5	barrels
Brine	0	barrels	0	barrels	0	barrels
Other	0	barrels	0	barrels	0	barrels

Description of Other Released Contaminant:

none

Inspected:

Written Report Received: 1/15/2013

Clean Up Concluded: 1/5/2013

Risk Evaluation:

No immediate risks.

Areal Extent:

Potential Environmental Impacts:

Release is being cleaned up. Area will be washed with fresh water. Cleanup should go well.

Action Taken or Planned:

Most of the oil stayed in the treater berm and flare pit. Vacuum truck will vacuum up oil and recycle. Fresh water will be used to wash the facility. All fluids recycled. Crews are working on cleanup.

Wastes Disposal Location: Recycled on site. Wash water will be taken to a approved disposal site.

Agencies Involved:**Updates**

Date: 1/4/2013 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Report states that "MOST" of release remained on location within the treater dike. However, there is enough doubt cast by the "most" to justify on-site confirmatory inspection.

Date: 10/2/2014 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

10/2/2014 at 13:14, on location. Some staining below treater within diking, but no staining is visible outside of dike. Dirt on wellpad has a blackish coloring due to pieces of coal evidently mixed with the dirt and scoria of the pad. Vegetation off wellpad is thick, and wheat field around location has been recently harvested. No visible lack of vegetation off the wellpad.